


Week of September 9 to September 14, 2019

Vibration monitoring was performed near the shoring removal associated with Structure A9 and A12.

Vibration Monitor UM13960:



Based on the data recorded by Vibration Monitor UM13960, it appears that the threshold amplitude of ground vibrations generated from the construction activities did not exceed the levels set forth in the U.S. Bureau of Mines (USBM) recommendation (RI 8507 1980) that are capable of producing damage to plaster and drywall in residential structures for the dates and times recorded.