


39th Avenue Greenway Vibration Monitoring

Week of October 1 to October 5, 2018

Vibration monitoring was performed at 3849 Gilpin Street, near the box culvert installation, near the sheet pile installation, near the work being performed near Coca-Cola, and on Denver Rock Drill property just off of East 40th Avenue.


3849 Gilpin Street (Zone 4)




Noise Monitoring:

Date	Leq (dB(A))	Lmax (dB(A))
October 1, 2018	60.9	91.8
October 2, 2018	58.9	84.7
October 3, 2018	62.5	83.9


Construction Vibration Monitor Near Box Culvert (Zone 2)



Sheet Piling (Zone 3)



Coca-Cola (Zone 7)



Denver Rock Drill (East 40th Avenue)

