

39th Avenue Greenway Vibration Monitoring

Week of December 3 to December 8, 2018

Vibration monitoring was performed near the box culvert installation.

Box Culvert (Zone 3)

