



**Week of September 1 to September 7, 2019**

Vibration monitoring was performed near the shoring removal associated with Structure A8 and A12.

Vibration Monitor UM13960:



Vibration Monitor BM9242:



Based on the data recorded by Vibration Monitor UM13960 and BM9242, it appears that the threshold amplitude of ground vibrations generated from the construction activities did not exceed the levels set forth in the U.S. Bureau of Mines (USBM) recommendation (RI 8507 1980) that are capable of producing damage to plaster and drywall in residential structures for the dates and times recorded.