


### 39<sup>th</sup> Avenue Greenway Vibration Monitoring

Week of January 14 to January 19, 2019

Vibration monitoring was performed near the shoring installation at the A-8 Structure and supplemental vibration monitoring adjacent to 3849 Gilpin Street.

#### Shoring Installation at A-8 Structure (Zone 4)



Noise Monitoring:

Date	Leq (dB(A))	Lmax (dB(A))
January 17, 2019	59.3	88.5
January 18, 2019	84.1	98.6
January 19, 2019	79.7	92.1

3849 Gilpin Street (Zone 4)

