


39th Avenue Greenway Vibration Monitoring

Week of January 21 to January 26, 2019

Vibration monitoring was performed near the shoring installation at A-8 and A-9 Structures.


Shoring Installation at A-8 Structure (Zone 3)




Noise Monitoring:

Date	Leq (dB(A))	Lmax (dB(A))
January 21, 2019	72.7	106.0
January 23, 2019	78.5	99.2

3849 Gilpin Street (Zone 4)




Shoring Installation Near A-9 Structure; 125 ft Southeast from the Corner of Williams Street and 39th Avenue (Zone 5)




Noise Monitoring:

Date	Leq (dB(A))	Lmax (dB(A))
January 25, 2019	69.6	94.2
January 26, 2019	66.9	79.4
January 26, 2019	67.6	88.5

Shoring Installation Near A-9 Structure; 150 ft Northeast from the Corner of Williams Street and 39th Avenue (Zone 6)



Shoring Installation Near A-9 Structure; Northwest Corner of Williams Street and 39th Avenue (Zone 5)



High Street Bar (Zone 7)

