


### 39<sup>th</sup> Avenue Greenway Vibration Monitoring

Week of April 21 to April 27, 2019

Vibration and sound monitoring were performed near the A-7 Structure shoring removal.

#### Northeast of the A-7 Structure (Zone 3)



Date	Leq (dB(A))	Lmax (dB(A))
April 26, 2019	69.9	87.4

South of the A-7 Structure (Zone 3)

