


39th Avenue Greenway Vibration Monitoring


Week of December 17 to December 21, 2018

Vibration monitoring was performed near the box culvert installation and near the shoring installation for Phase VI (Smith Road and Dahlia Street).

Box Culvert (Zone 3)



Shoring Installation at Phase VI (Zone 17)



Noise Monitoring:

Date	Leq (dB(A))	Lmax (dB(A))
December 17, 2018	80.1	105
December 18, 2018	87.2	106.4
December 19, 2018	85.9	105.3
December 20, 2018	87.1	103
December 21, 2018	85.2	115.8