

Existing Conditions - Maintenance Area and Patrick House

- P** PARKING
- TH** TRAILHEAD
- BS** BUS STOP
- RC** RV CAMPING
- DS** DUMP STATION
- CS** CAMPSITE
- HT** HIKING TRAIL
- SGT** SELF GUIDED TRAIL
- O** OVERLOOK
- OC** OFFICE/CHECK IN
- PT** PICNIC TABLE
- FR** FIRE RING/GRILL
- S** SHELTER
- SWT** SHELTER W/ TABLES
- FRS** FLUSH RESTROOMS
- RAS** RESTROOM AND SHOWER
- PT** PIT TOILET
- G** GATE
- FB** FOOT BRIDGE
- EB** EXISTING BUILDING
- S** SHELTER



1. BISON UNDERPASS LOOKING SOUTH



2. EXISTING WINDMILL



3. BISON FENCE AND UNDERPASS LOOKING WEST



4. EXISTING ROAD CONDITIONS LOOKING EAST



5. EXISTING ROAD CONDITIONS LOOKING SOUTHWEST



6. ROAD ENTERING MAINTENANCE FACILITY AND PATRICK HOUSE



7. EXISTING SIGN AT THE PATRICK HOUSE



8. HISTORIC PATRICK HOUSE



9. MAINTENANCE AREA LOOKING WEST



10. MAINTENANCE BUILDING BEHIND THE PATRICK HOUSE



11. MAINTENANCE AREA LOOKING WEST



12. MAINTENANCE AREA



13. OLD FARM EQUIPMENT AND STORAGE CONTAINER



14. MAINTENANCE YARD LOOKING WEST



15. MAINTENANCE BUILDING



16. MAINTENANCE BUILDING AND BARN



17. OLD FARM EQUIPMENT



18. MAINTENANCE STORAGE BUILDING



19. STORAGE SHED BEHIND THE PATRICK HOUSE



20. VIEW OF THE MAINTENANCE AREA LOOKING WEST



21. INFORMAL PARKING AREA AND FOR BISON VIEWING

EXISTING SITE USE SUMMARY

- HISTORIC PATRICK HOUSE CURRENTLY USED FOR CARETAKERS RESIDENCE
- DENVER MOUNTAIN PARKS MAINTENANCE AREA CENTRAL LOCATION
- BISON VIEWING ACCESS
- BISON UNDERPASS UNDER I-10
- PARK LOOP ROAD

YOUR INITIAL THOUGHTS/IDEAS FOR POTENTIAL IMPROVEMENTS



Genesee Park and Katherine L. Craig Tract

July, 2012

Park and Trail Improvement Plan

